

Soil Test Pit Descriptions

Location: 281 Littleworth Rd
Madbury, NH

Date: 06/22/2015
Client: Garvey

Evaluator: Marc Jacobs, CSS #038 *MJ*

Witness: Mike Cuomo



Test Pit 5 (Deerfield)

- 0" 10YR 3/3, loamy fine sand, weak fine granular, moist friable
- 10" 10YR 5/6, loamy sand, massive, moist friable, 5% 10YR 6/2 redoximorphic depletions and 5% 7.5YR 5/6 redoximorphic concentrations at 24" = estimated seasonal high water table (ESHWT)
- 30" 10YR 5/3, sand, single grain/massive, moist friable, discontinuous lenses of very fine sand and silt loam with common to many coarse redoximorphic concentrations and depletions
- 76" Terminated, no refusal or observed free water