



25 Nute Road
 Dover, NH 03820
 tel: (603) 659-8939
 fax: (603) 834-9176
 www.atlanticsurveyco.com
atlanticsurvey@comcast.net

Date: 2/8/2017

Project No. 16127

Location: 55 Evans Road, Madbury, NH

Observed By: Adam R. Fogg, NH Subsurface System Designer No. 1377

Observed By: Michael Cuomo, R.C.C.D.

Test Pit No.: 1

<u>DEPTH (IN)</u>	<u>DESCRIPTION</u>
0-10	dark brown (10YR 3/3) fine sandy loam, friable, granular
10-16	yellowish brown (10YR 5/6) fine sandy loam, friable, granular
16-32	light olive brown (2.5Y 5/6) sand, loose, single grain
32-76	light yellowish brown (2.5Y 6/4) silt loam, firm, massive

Seasonal High Water:	32	Observed Water:	none
Restrictive Layer:	32	Bedrock:	none



25 Nute Road
 Dover, NH 03820
 tel: (603) 659-8939
 fax: (603) 834-9176
 www.atlanticsurveyco.com
atlanticsurvey@comcast.net

Date: 2/8/2017

Project No. 16127

Location: 55 Evans Road, Madbury, NH

Observed By: Adam R. Fogg, NH Subsurface System Designer No. 1377

Observed By: Michael Cuomo, R.C.C.D.

Test Pit No.: 2

<u>DEPTH (IN)</u>	<u>DESCRIPTION</u>
0-10	dark brown (10YR 3/3) fine sandy loam, friable, granular
10-20	brownish yellow (10YR 6/6) stony fine sandy loam, friable, granular
20-48	light yellowish brown (2.5Y 6/4) gravelly sand, loose, single grain
48-62	olive brown (2.5Y 4/4) gravelly sand, loose, single grain w/redox

Seasonal High Water:	48	Observed Water:	none
Restrictive Layer:	none	Bedrock:	none