



Schreiber
 42 Cherry Lane
 Tax map/lot: 6/13
 RCCD #MA6-13-L13

Test Pit	Seasonal High Water Table	Bedrock	Total Depth	Pass/Fail
1 Lot "B"	26"	yes	30-48"	fail
2 Lot "B"	30"	yes	38-54"	fail
3 Lot "B"	20"	yes	36"	fail
4 Lot "A"	32"	yes	60"	pass
5 Lot "A"	24"	yes	62"	pass
6 Lot "A"	21"	no	60"	fail
7 Lot "A"	13"	no	55"	fail
8 Lot "B"	26"	yes	48"	fail

Test pits 4 and 5 meet town and state soil requirements for wastewater disposal.

Test pits 3, 6, and 7 do not meet local soil requirements because the water table is less than 24 inches from the surface.

Tests pits 1, 2, 3, 7, and 8 do not meet local soil requirements because bedrock is less than 60 inches from the surface.

The wetlands were not yet identified at the time this work was done.